

# JOG and Teretek® Re-supports and Re-levels Milton Keynes Commercial Property

PROJECT PROFILE

2018-2017UK

mainmark



## INDUSTRY

Commercial

## STRUCTURE

Office Building

## PROBLEM

Subsidence

## LOCATION

Milton Keynes, UK

## DURATION / YEAR

7 Days / 2018

## TECHNOLOGY

JOG and Teretek®

## BUSINESS UNIT

Mainmark (UK)

## Summary

Following the record high temperatures of the summer of 2018, [MK Surveys](#), (the landlord) an independent survey and geospatial specialist, noticed the small amount of subsidence at one of its commercial office buildings in Kiln Farm, Milton Keynes, was greatly accelerating, causing significant damage to the property and external windows.

As well as acting as both an office for the tenant's employees and general storage, the building also welcomed large numbers of visitors for external meetings and interactive sessions. Due to the extended heatwave and mature trees growing in close proximity, the subsidence had rapidly worsened and was now starting to impact the employee's working environment; including the use of the windows. The tenant raised concerns with MK Surveys about draughts and dampness and asked them to urgently fix the problem and replace the windows. To help ensure the ongoing health and safety of the tenants' employees, MK Surveys first decided to correct the underlying subsidence by strengthening the ground and re-level the building, rather than just replacing the windows. This would also avoid damage to any new windows installed.

## Objectives

Due to both the urgency of the project and to minimise business interruption, MK Surveys called upon the expertise of [Mainmark](#), to help strengthen the ground beneath the property's foundation and raise it back to level. Mainmark's award-winning ground improvement solutions offer many benefits to commercial properties beyond traditional underpinning, including their speed and non-invasive qualities; saving companies both time and money.

Upon inspecting the property, the Mainmark team discovered that the lowest corner of the building had subsided by 94mm and the perimeter pad foundation

## JOG and Teretek® Re-supports and Re-levels Milton Keynes Commercial Property continued

had rotated outwards resulting in a discrepancy of 50mm between the internal and external levels. This required considerable care and precision when rotating the foundation pad back to horizontal, before final lifting to ensure both the external perimeter and internal flooring were raised by equivalent amounts.

### Solution

To ensure both the internal and external foundations were equally re-levelled and correction of the rotation was achieved, Mainmark utilised two of its advanced solutions simultaneously; JOG Computer-Controlled Grouting for the main lift and re-level around the perimeter, and Teretek® resin injection for ground improvement and void filling under the internal floor slabs.

The precise degree of control offered by Mainmark's cost effective and time efficient JOG technology enabled the substantial lift of the unit's foundations, ensuring the integrity of the building remained intact.

Multiple injection ports were installed through the concrete foundation and structural pads along the subsided section of the building, through which the JOG high mobility cementitious grout was introduced under computer control. This enabled Mainmark to gradually and precisely lift the building in a controlled manner without causing any business interruption. The spacing and placement of the injection ports were tailored to accommodate the structural elements of the foundation, while the grout was mixed and pumped from self-contained units stationed behind the building ensuring no business interruption.

While the JOG technology raised the unit's external walls, Mainmark's proprietary Teretek resin injection solution was used to fill any voids under the internal floor slab, thus raising the floor to level with the external walls. Teretek is unique in that it delivers both ground improvement and re-levelling in a fast, non-invasive process.

Within just seven days Mainmark raised and re-levelled the structure by 86mm, the maximum deemed appropriate without negatively impacting other factors such as the roof and internal fixtures and fittings.

The non-invasive and quick solutions offered by Mainmark allowed the landlord to replace the damaged windows within the commercial property in a quick timeframe, resulting in a satisfied tenant and a safe working environment for employees.

Stuart Dimond, Director at MK Surveys said: *"As time and business interruption were our two main concerns prior to this project, we selected Mainmark to correct the underlying subsidence issue our Kiln Farm building was experiencing as they had both the skills and advanced solutions in order to get the job done in a timely manner with minimal disruption. We are delighted with the results and the feedback has been incredible. We were astonished that it took just seven days to fix the issue and ensure the ongoing health and safety of our tenants' employees."*



Mainmark engineers monitoring non-invasive re-levelling



External wall cracks caused by subsidence